REMARKS/ARGUMENTS

The enclosed replacement drawing sheets for FIGS. 1-7 include formally drafted diagrams, numbering, etc.

No new matter has been entered by the above amendments.

The Applicant respectfully requests that the replacement drawing sheets be included in the application so that the patent issues with these replacement sheets.

Respectfully submitted,

McCarthy Tétrault LLP

Date: May 2, 2006

 $\mathbf{B}\mathbf{y}$

Joseph P. Conneely

Registration No. 54,883 Telephone: (416) 601-8179

Fax: (416) 868-0673


McCarthy Tétrault LLP Box 48, Suite 4700 66 Wellington Street West Toronto Dominion Bank Tower Toronto, Ontario, Canada M5K 1E6


AMENDMENTS TO THE DRAWINGS:


The attached sheets of drawings include changes to FIGS. 1-7. These sheets, which include FIGS. 1-7, replace the original sheets including FIGS. 1-7. In FIGS. 1-7, the hand drawn diagrams, numbering, etc., have been replaced with formally drafted diagrams, numbering, etc.

Attachment: Replacement Sheets (i.e., 1/7 to 7/7)

Annotated Sheets Showing Changes (i.e., 1/7 to 7/7)








MPLS Frame 312	
data	header 2ndLabel 1stLabel
314	316 320 318

Fig. 3

Annotated
Sheet

Drawing Made
Formal
3/-




ATH network 102(2) 520 ATHOAM AIS SIZ 122(2) BILL . tune | 204 594 Cad MALS OAM FDI S10) . Gult 500 Z87 Figure S (00/ 150 MR'S 202 metwork 104 156200 MPLSOAM BDI 516 508 HPLS Ead 404(1) ATM/MPLS edgeswitch ATH Cared 400(1) ATT retwork 102(s) ATH OAH RDI SIY 522

20943140.1

Annotated Sheet

Drawing Made



Annotated Fig. 7 Drawins Made Unknown State 702 Defect Declared Defect Not Detected Defect Declared Defect State οK state 706 704 Defect Cleared

> MPLS OAM state Machine 604